

RECEIVED

JAN 23 1992

DIVISION OF  
OIL GAS & MINING

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) JAN 1991 To (mo./yr.) DEC 1991
2. DOGM File Number: M10451024
3. <sup>Plant</sup> Mine Name: Marblehead Mountain Facility
4. Mineral(s) <sup>Processed</sup> Mined: Limestone Dolomite
5. Legal Description (Location of Lands Affected):  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, Section 2, Township T-1-N, Range R-9-W  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_\_, Township \_\_\_\_\_, Range \_\_\_\_\_  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_\_, Township \_\_\_\_\_, Range \_\_\_\_\_
6. Name of Operator or Company: Materials Energy Research & Recovery Corp  
Marblehead Mountain Facility
7. Permanent Address: P.O. Box 596  
GRANTSVILLE UTAH 84029

8. Company Representative (or designated operator):

Name: Jack Minchey  
Title: Facility Manager  
Address: P.O. Box 596 Grantsville UT 84029  
Phone: 801 355 1984

☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the ~~mine~~<sup>plant</sup> active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was ~~mined~~<sup>processed</sup>? 68734 Ton
3. How much new or additional acreage was affected during past year? no changes
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.  
NO changes
5. How much acreage was reclaimed during past year? started reclaiming about 10 acres
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
we are in the process of finishing, the 10 acres started last year plans labeled Areas 1 and 2 on drawing # MM-01. The area is sloped to a 3-1 slope and 18" cover of South pile of limestone fines are on we have contracted to finish the top 6" of cover, seeding and mulch, will be - 2. Finish as soon as possible

7. What is the total disturbed acreage at years end? Approximately 10 acres
8. Briefly summarize mining and reclamation planned for the upcoming year.  
Finish per drawing # MM-01, drainage ditches  
Top soil cover per agreement Muck seeding and  
Fence

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Jack Minchey

Title of Operator: Facility Manager

Signature of Operator: Jack Minchey

Date: 1-21-92

revised 2-10-92

jb  
MR-AR